

Blower
Relay
not
function
warrant
part
LABOR
CHARGE
175⁰⁰

upon arrival had consultation w/ customer, customer state

29.95

FAN RUNS NOT BLOWING COLD AIR. My

Diagnostic of unit revealed unit outside

not coming on, need to trouble shoot power

loss to outside unit, trouble shoot at 185⁰⁰

170⁰⁰

Req 1/2 Hr minimum of (1) 1/2 Hr

Troubleshoot revealed

Kenner Perkins

transformer not functioning properly not

400⁰⁰

allowing low voltage to reach other components

175⁰⁰

also contactor or condenser not functioning

29.95

properly, as a start to remedy problem need

745⁰⁰

to replace transformer & contactor. Kenner Perkins

MANU
FACTURE

WARRANTY OF PART CONTACTOR 175⁰⁰ LABOR 225⁰⁰ LABOR

LABOR