

Service Call/Diagnostics Upstairs	29.95
Customer stated upstairs unit not cooling. Customer approved diagnostic	
Diagnostics found upstairs system con-	
denser contactor closed, condenser fan	
& compressor not operating. Customer	
approved troubleshooting service. Troubleshooting found capacitor not starting fan or compressor. Customer approved capacitor installation for 472.82. Upstairs operating. Customer approving contactor replacement, & coil cleaning on both condensers at a discount of 50% plus for 500 ⁰⁰ Mech code 320	